

Message

From: Castellana, Ben [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=A5E5385776764CC4B9E1A718B4090A30-CASTELLANA,]
Sent: 8/20/2019 4:45:26 PM
To: Mel Khachatourian [mel.khachatourian@lacity.org]
CC: Sam Portillo [sam.portillo@lacity.org]; Bruce Todd [bruce.todd@lacity.org]; Hector Rodriguez [hector.rodriguez@lacity.org]; Mario Cuevas [mario.cuevas@lacity.org]
Subject: Re: 216 W Slauson - red tag report

Received, and thank you!

Sincerely,

Ben Castellana Ph.D.
On-Scene Coordinator
US EPA Region 9
Superfund Emergency Response
(562) 305-0694

On Aug 20, 2019, at 7:08 AM, Mel Khachatourian <mel.khachatourian@lacity.org> wrote:

Good morning Mr. Castellana,

Please find the attached issued order that addresses the site condition.
Also, please contact the registered owner of the property to obtain a demolition permit form LADBS plan check office if that serves the best interest in reference to your inquiry.

Thank you,

Mel S. Khachatourian
Ladbs BMI Inspector
Code Enforcement/South
4301 S. Central Ave.
Los Angeles, Ca. 90011
(213)-978-4494
Email : mel.khachatourian@lacity.org

On Mon, Aug 19, 2019 at 8:07 AM Sam Portillo <sam.portillo@lacity.org> wrote:

----- Forwarded message -----

From: **Bruce Todd** <bruce.todd@lacity.org>
Date: Mon, Aug 19, 2019 at 7:56 AM
Subject: Fwd: 216 W Slauson - red tag report
To: Portillo, Sam <sam.portillo@lacity.org>

FYI please respond to them, .Thanks

Principal Inspector Bruce Todd
Los Angeles Department of Building & Safety
Code Enforcement Bureau
1968 W Adams Blvd Suite G-16
Los Angeles, CA 90018
(213)978-4502

----- Forwarded message -----

From: **Hector Rodriguez** <hector.rodriguez@lacity.org>
Date: Fri, Aug 16, 2019 at 11:12 AM
Subject: Fwd: 216 W Slauson - red tag report
To: Bruce Todd <bruce.todd@lacity.org>

----- Forwarded message -----

From: **Castellana, Ben** <castellana.ben@epa.gov>
Date: Thu, Aug 15, 2019 at 7:54 AM
Subject: 216 W Slauson - red tag report
To: hector.rodriguez@lacity.org <hector.rodriguez@lacity.org>

Hi Mr. Rodriguez,

I'm the Federal On-Scene Coordinator overseeing the cleanup of the tanker explosion and gasoline release that caused a fire at a residential structure at 216 W Slauson Ave in Los Angeles. The structure is red-tagged by your department, and I need a formal report from your office to assist with getting the structure demolished.

To add to our issues, there are homeless people breaking into the house, creating a nuisance and a greater threat of fire or explosion due to the presence of gasoline vapors at the site.

Can you help and or direct me to an individual who can provide the report? This is a time-critical situation, so I appreciate any help you can provide.

Sincerely,

Ben Castellana Ph.D.
On-Scene Coordinator
US EPA Region 9
Superfund Emergency Response
(562) 305-0694

--

Thank You,

Hector Rodriguez
BMI Inspector
LADBS/CEB
4301 S Central Ave
Los Angeles, CA 90011
213-978-4496

<216 W. SLAUSON AVE-1.pdf>

<216 W. SLAUSON AVE-2.pdf>